

T12 LCD Power Tester

Easily, Effectively, Accurately to test PSU output

12 ways to test your power supply:

- 24-pin connector
- 20-pin connector
- 4-pin Molex connector
- SATA connector
- 6-pin PCI-Express connector
- 8-pin connector
- 4-pin connector
- Floppy connector
- ATX output connectors check
- Lower voltage detected alarm
- Over voltage alarm
- No voltage detected alarm



A must have tool for any computer enthusiast and engineer

Recom T12 detects a bad power switch, incorrect voltages & blown PSU before putting it into a PC

Pocket size, Light-weight with aluminum housing
LCD Display with Blue backlight

